

Фото	Задача 1. Студенту надається фото об'єкту, де виконано роботи по термо модернізації. Необхідно описати дефекти утеплення фасаду, покрівлі, перекриття підвалу, цоколю тощо.
1	 The photograph shows a two-story building with a yellow and pink facade. The ground is covered in snow. A set of stairs leads to the entrance, which is covered by a small white canopy. There are several windows visible on both floors. The building appears to be a residential or institutional structure.

2



3



4



5	
6	


7



8



9



10	 A photograph of an exterior wall. The left portion of the wall is painted a light green color, while the right portion is a light blue color. Two white-framed windows are visible at the top of the frame, one on each side of the color transition. The wall surface appears to be a standard plaster or render.
11	 A close-up photograph of the corner where the green wall from the previous image meets a grey wall. The joint is uneven and shows signs of poor workmanship, including peeling paint and exposed substrate. A thin crack runs diagonally across the grey wall. The textures of the two different wall finishes are clearly visible.

12



13



14



15



16



17



18



19



20



21



22




23



24



25



26




27



28



29



30



31



32



33



34



35




36



37



38



39



40



41




42



43



44



45



46



47

