

Фото	Задача 1. Студенту надається фото об'єкту, де виконано роботи по термомодернізації. Необхідно описати дефекти утеплення фасаду, покрівлі, перекриття підвалу, цоколю тощо.
1	
2	

3



4



5



6




7



8



9



10



11




12



13



14



15



16



17



18



19



20



21



22



23



24



25



26



27



28



29



30



31



32



33



34



35




36



37



38



39



40



41	
42	

43



44



45



46



47	
48	

49

