

фото	Задача 1. Студенту надається фото об'єкту, де виконано роботи по термомодернізації. Необхідно описати дефекти утеплення фасаду, покрівлі, перекриття підвалу, цоколю тощо.
1	
2	

3



4




5



6



7



8	
9	

10



11



12



13



14



15



16



17



18



19



20



21



22



23



24



25



26



27



28



29



30



31



32



33



34



35



36



37



38



39



40



41



42



43



44



45



46



47



48

